

ADDITIONAL PHOTOS FOR USACE EMERGENCY PERMIT: SNUG HARBOR – STEAMBOAT SLOUGH MARCH 2017

The below photos were taken by drone on March 11, 2017. Notations have been added to the photos to show the locations of washed away bank, former trees that fell and had to be removed, or trees and logs clogging the cove area.



8 trees fell over
fall - winter months
and in Feb 2017
at least 6-8 feet of
bank along this area
was washed away





Above photo shows Snuggle Inns 9, 10, 11 and then the leaseholder park model RV cottages. Blue circles show the locations of trees that died 2016-2017 and fell, or had to be removed before falling.

North portion of property, from boat launch area to office & gas dock to the gate entrance area:





Above photo show the section between the fuel barn to RV site 19 and the boat launch area.



Above photo shows the section from the fuel barn north to RV site 2, where at least 8 feet of bank and man trees were lost.